TIME-SERT® FORD TRITON M16x1.5 3 VALVE SPARK PLUG REPAIR KIT P/N 3221

 WARNING –
Cutting tools may shatter if broken. The wearing of safety glasses is required in the vicinity of their use.

- CUTTING FULID -A Cutting Fluid is necessary for reaming and tapping. (WD40)

- AIR RATCHET -Use of an air ratchet at slow speed will help speed up the reamer tool.



This is not recommended as an "Over the fender repair"

Due to the long pilots on the reamer and tap, there is a possibility of the pilot breaking off and falling into the engine.

Before you proceed:

Make sure that the head is raised above the working surface at least an inch or 25mm so that the pilots on the tap and reamer tools have clearance as to not hit the surface below. If repairing on a work bench this can be accomplished by using 2 short pieces of 2"x 4"wood to raise the head from the surface then secure head in place.

Instructions are using a block of aluminum, for better viewing. This repair can be done on the vehicle at your own risk.

1) Using the wrench provide, place the reamer into square of the wrench and tighten the setscrew to secure the reamer in place. The pilot on the reamer will keep the newly reamed hole square to the original threads. Picture A. Ream the hole until the black stop collar bottoms out on the hole and spins freely. This will create a countersink for the

flange of the insert. Picture B.








2) Using the wrench provided, place the tap into the square of the wrench and tighten the setscrew to secure the tap in place. Picture C.

Tap the hole to the full depth permitted by the tool. The tap should "stop" or bottom out as it comes in contact with the bottom of the newly reamed hole. Picture D.

Use contact or brake cleaner to thoroughly clean out any remaining chips and oil.







www.timesert.com