



NUMBER: 24-001-04

GROUP: Heating & Air Conditioning

DATE: January 20, 2004

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of DaimlerChrysler Corporation.

SUBJECT:

New HVAC Sub-Assembly Replaces Blend Or Recirc Door Components

MODELS:

1999 - 2004 (WJ/WG) Grand Cherokee (All Markets)

DISCUSSION:

New HVAC sub-assemblies are now available in the Mopar Parts system. Each new sub-assembly consists of several individual components. The new sub-assemblies improve component reliability. It is recommended that the respective sub-assembly be installed if a blend air door(s), a recirculation door, a door link, or a sub-assembly housing requires replacement. The following table provides the part numbers for the new HVAC sub-assemblies.

| Model Year | Drive | HVAC Control | Sub-Assembly | Part Number |
|------------|-------|-------------------------|-------------------|-------------|
| 99-01 | LHD | Auto Zone Control (AZC) | Mid-Case Blend | 05134349AA |
| 99-01 | LHD | Manual | Mid-Case Blend | 05134351AA |
| 99-01 | RHD | Auto Zone Control (AZC) | Mid-Case Blend | 05134348AA |
| 99-01 | RHD | Manual | Mid-Case Blend | 05134350AA |
| 02-04 | LHD | Auto Zone Control (AZC) | Mid-Case Blend | 05134353AA |
| 02-04 | LHD | Manual | Mid-Case Blend | 05134355AA |
| 02-04 | RHD | Auto Zone Control (AZC) | Mid-Case Blend | 05134352AA |
| 02-04 | RHD | Manual | Mid-Case Blend | 05134354AA |
| 99-04 | LHD | Auto Zone Control (AZC) | Air Recirculation | 05134347AA |
| 99-04 | RHD | Auto Zone Control (AZC) | Air Recirculation | 05134346AA |

POLICY:

Information Only

063198

DaimlerChrysler Corporation
Dealer Technical Operations